



WORLD CLASS
I N D U S T R I E S

World Class Industries

Supplier Quality Manual

October 10, 2023



WORLD CLASS INDUSTRIES

TABLE OF CONTENTS

- 1 Vision
- 2 Purpose
- 3 Scope
- 4 General Quality Requirements
- 5 Control of Documents and Records
- 6 Material and Process Control
- 7 Non-Conforming Material
- 8 Product Packaging
- 9 Delivery
- 10 Right of Entry
- 11 Corrective Action Request (CAR)
- 12 Risks
- 13 Continuous Improvement
- 14 External Providers

This manual is not intended to replace a supplier's existing quality system. Suppliers should perform a self-evaluation to determine where their quality system and supply chain align with this manual. **As included in the terms and conditions, acceptance of a World Class Industries purchase order constitutes acceptance of the requirements of this manual.** Suppliers should require similar terms and conditions with their supply chain. Suppliers are expected to have procedures in place designated to ensure that they comply with the laws, rules, and regulations of the countries and locations in which they operate.

1 Vision

Our vision is for all World Class Industries (WCI) Suppliers to implement and maintain a quality system that allows them to produce and deliver to World Class Industries globally competitive products and services that are clearly seen by our customers as superior in performance and value.

2 Purpose

The purpose of this Supplier Quality Manual is to define the Quality Requirements that World Class Industries requires of their suppliers upon acceptance of a WCI purchase order. It also contains guidelines to define the business relationship between World Class Industries and its suppliers.

3 Scope

This manual applies to all World Class Industries suppliers of products and services. This includes suppliers to all WCI locations as well as shipments going directly to World Class Industries' customers. Suppliers who outsource any processes are responsible for ensuring that their sub-suppliers meet all print and specification requirements and that these suppliers are able to provide inspection and quality data for their processes.

4 General Quality Requirements

All World Class Industries suppliers should have a Quality System which demonstrates that acceptable quality standards can be maintained. Such a quality system must be capable of providing parts with



WORLD CLASS INDUSTRIES

PPAP submittal and maintaining and providing quality records which ensure that all production parts are acceptable for use as intended. These quality records include:

- Production Inspection records (ISIR)
 - Full, dimensional layout using calibrated measurement tools
 - Bubble print with correct revision, highlighting all dimensions that were documented
 - Supporting data or documentation for all additional customer-specific requirements on the print
- Control Plan
 - Defined in the AIAG manual
- Receiving inspection records (material certifications)
 - Date of certification
 - Supplier name and address
 - Heat, batch, or lot number of the material
 - Type and grade of the material
 - Chemical composition of the material
- Verification Warrant
 - Part number and correct revision
 - Drawing number (if applicable)
 - List of submittals (what PPAP documents are being submitted along with Warrant)
 - Manufacturing facility
 - Quality contact name and phone number
 - Indication that all requirements are met
 - Any exceptions that the supplier is taking to the requirements
 - Date of submittal
 - Signature of Quality representative

Certain parts or assemblies may require additional quality documentation. These requirements will be identified by a WCI Quality Representative at the time of final design review or soon after a purchase order is placed.

These documents may include:

- Design and Process Failure Modes and Effects Analysis
- Process Flow Diagrams / Process Map
- Measurement Systems Analysis Data (Gage R&R for Key Characteristics)
- Capability Studies and SPC Data
- Special Process Data (i.e. Heat Treat, Plating, Painting, etc.)
- Appearance Approval Report
- Functional and Performance Test Data

WCI will not accept PPAP charges if they were not included in the original quote. All required documents shall be submitted to World Class prior to shipping parts. All documents must be submitted in English.



WORLD CLASS INDUSTRIES

It is the responsibility of the Supplier to verify that the substances listed in the attachment below are not in any products, parts, components, or materials supplied to WCI at or above the referenced threshold.

[restricted materials list suppliers.pdf \(worldclassind.com\)](#)

Regulatory Compliance information (REACH, RoHS, Conflict Minerals, etc.) shall be provided to WCI when requested.

5 Control of Documents and Records

Suppliers and sub-tier suppliers shall establish and maintain records to provide evidence of conformity to requirements.

Process Control Documents shall be current and followed.

Suppliers are responsible for using the most current standards, to understand them, and to review changes to standards.

All quality and supply chain records shall be kept for at least three years unless otherwise agreed to by World Class Industries.

6 Material and Process Control

Quality shall be controlled through process control methods such as mistake proofing, checking fixtures, gaging, process/product audits, or other methods.

Product identification shall be maintained through all stages of receipt, production, and delivery.

Supplier shall maintain inspection and test results to be available for review by WCI.

Instructions for rework and repair, including re-inspection requirements, shall be accessible to and utilized by appropriate personnel.

A maintenance system shall be implemented for equipment including, but not limited to, production machines, tooling, facilities, and test equipment.

The supplier shall establish and maintain documented procedures for the calibration, control, and maintenance of measuring, inspection, and test equipment. This includes reaction plans when a gauge is found out of calibration.

Processes should be developed to ensure that employees are enabled to do the job right every time. This includes, but is not limited to data collection systems, training, and error-proofing techniques.

An internal audit program shall be documented and performed annually on the quality system.

Suppliers are expected to manage changes through a structured process.

Supplier shall notify WCI of the following changes: Location of manufacturing, materials used in manufacturing the part(s), and production processes and/or equipment affecting the manufacture of product or services. Once the change is approved, new PPAP data will be requested before the product is approved to ship.



WORLD CLASS INDUSTRIES

7 Non-Conforming Material

The supplier is responsible for performing adequate inspection and/or verification activities to ensure that WCI requirements are met. If a non-conformance is identified, the supplier will be notified by World Class Industries to provide immediate containment and support to resolve the problem.

Within 24 hours of notification of non-conforming parts, the supplier must:

- Implement Containment at their facility
- Identify a plan for Containment at customer
- Report containment methods and methods to identify certified material
- Inform WCI of the plan to replace suspect material
- Identify short-term corrective action

If the supplier wishes to have non-conforming material returned, they must provide a Return Material Authorization (RMA) within 24 hours of notification.

Suitable means shall be used to identify and segregate non-conforming product.

If inspection or sorting is performed by WCI or a 3rd party, all related costs will be charged to the supplier. A Cost of Poor Quality Charge may also be applied.

8 Product Packaging

World Class Industries expects products to be packaged in such a way to ensure delivery of product intact and in usable condition.

Parts must be rust-free at the time of receipt at the Ship-To facility. They must be capable of staying rust-free indoors at the receiving facility for 90 days in original, unopened supplier packaging.

All parts must meet the customer specifications. Additionally, Hoses, Lines, and Hydraulic or Pneumatic fittings must be capped.

In accordance with USDA regulations, all pallets must be approved for use and free from infestations.

9 Delivery

All deliveries are expected to be 100% on time based on delivery dates agreed upon when the purchase order is issued and acknowledged. On-time for domestic suppliers is defined as '3 days prior/0 days after' the agreed upon delivery date. On-time for international suppliers is defined as '7 days prior/0 weeks after' agreed upon delivery date. Unless prior arrangements are made with World Class Industries, payment terms will be effective as of the original due date and not any early ship dates.

It is the supplier's responsibility to inform World Class Industries of any change in ship dates. World Class will accommodate changes in ship dates if possible.

Suppliers are expected to have the resources necessary (personnel, property, facilities, equipment, and materials) to supply the products required to accommodate WCI's PO requirements. The supplier should provide for fluctuations in requirements due to scheduling changes.

10 Right of Entry

World Class Industries may request access to the supplier's facility to perform inspections or audits to verify the quality of work and records.

11 Corrective Action Request (CAR)



WORLD CLASS INDUSTRIES

A supplier Corrective Action Request may be issued for non-conformances. The supplier is responsible for identifying the root cause of the problem and implementing a corrective action to prevent recurrence. Supplier shall use a documented problem-solving process such as 8D or equivalent.

12 Risks

Supplier shall identify internal and external risks to the manufacturing processes and infrastructure essential to maintain production output. Contingency plans shall be identified and a notification plan to WCI shall be documented.

13 Continuous Improvement

Supplier shall have posted and understandable performance metrics with goals. Actions shall be taken if the goals aren't being met.

A formal process shall be in place where data is collected, analyzed, and used to define continuous improvement activities

14 External Providers

The supplier shall determine criteria for the evaluation, selection, monitoring of performance, and re-evaluation of external providers. The supplier shall retain documented information of these activities and any necessary actions arising from the evaluations.